

Upgrade Notice August 1 to 31, 2019

Summary of upgrades for various models in August

Mitsubishi V3.10 upgrade Notice

- 1.Added six special functions for Mitsubishi: EPB reset, injector coding, DPF reset, oil reset, TPMS, SAS reset.
- 2.Fixed the crash of 2010 Mitsubishi Lancer during test.
- 3.Fixed 2006 Mitsubishi Galant engine error code P000 repeated and undefined, and fixed the AT trouble code not fully cleared problems.
- 4.Fixed Mitsubishi Eclipse Cross auto transmission system communication failure issue.
- 5.Fixed 2008 Mitsubishi Grandis engine read two more P0000 fault codes and rear right air conditioner fault codes clearing issue.
- 6.Added P0140 fault code for 2005 Mitsubishi Outlander engine.
7. Solve the problem that the Mitsubishi Outlander local interconnect network control system has a fault code and the clear code cannot be cleared in 2018.

Chery V3.50 upgrade Notice

1. Added Chery: Arrizo EX/GX, Tiggo 5x (T19), Tiggo 8 a total of 3 models;
2. Added Karry: K50 electric vehicle (Q26EV), K60 2018 model, K60 country five 1.5T model, K60EV, Q22LEV electric vehicle (Zhongbo) / Youyou EV, Q22LEV electric vehicle (autonomous) a total of 6 models;
3. Added Chery_EV: S32EV, Arrizo 5e (year-old car), Arrizo 7E, Tiggo 3xe, a total of 4 models;
- 4.Added Chery and Link Car (Karry, Riich, Rely, Chery_EV), anti-theft, gearbox matching, brake exhaust, vehicle maintenance function reset, EPB initialization, writing VIN code, 5 models Special functions such as tooth learning;
5. Added the automatic positioning function of each car.

Chery EV V3.50 upgrade Notice

1. Added Chery: Arrizo EX/GX, Tiggo 5x (T19), Tiggo 8 a total of 3 models;
2. Added Karry: K50 electric vehicle (Q26EV), K60 2018 model, K60 country five 1.5T model, K60EV, Q22LEV electric vehicle (Zhongbo) / Youyou EV, Q22LEV electric vehicle (autonomous) a total of 6 models;
3. Added Chery_EV: S32EV, Arrizo 5e (year-old car), Arrizo 7E, Tiggo 3xe, a total of 4 models;
- 4.Added Chery and Link Car (Karry, Riich, Rely, Chery_EV), anti-theft, gearbox matching, brake exhaust, vehicle maintenance function reset, EPB initialization, writing VIN code, 5 models Special functions such as tooth learning;
5. Added the automatic positioning function of each car.

Karry V3.50 upgrade Notice

1. Added Chery: Arrizo EX/GX, Tiggo 5x (T19), Tiggo 8 a total of 3 models;
2. Added Karry: K50 electric vehicle (Q26EV), K60 2018 model, K60 country five 1.5T model, K60EV, Q22LEV electric vehicle (Zhongbo) / Youyou EV, Q22LEV electric vehicle (autonomous) a total of 6 models;
3. Added Chery_EV: S32EV, Arrizo 5e (year-old car), Arrizo 7E, Tiggo 3xe, a total of 4 models;

- 4.Added Chery and Link Car (Karry, Riich, Rely, Chery_EV), anti-theft, gearbox matching, brake exhaust, vehicle maintenance function reset, EPB initialization, writing VIN code, 5 models Special functions such as tooth learning;
5. Added the automatic positioning function of each car.

Rely V3.50 upgrade Notice

1. Added Chery: Arrizo EX/GX, Tiggo 5x (T19), Tiggo 8 a total of 3 models;
2. Added Karry: K50 electric vehicle (Q26EV), K60 2018 model, K60 country five 1.5T model, K60EV, Q22LEV electric vehicle (Zhongbo) / Youyou EV, Q22LEV electric vehicle (autonomous) a total of 6 models;
3. Added Chery_EV: S32EV, Arrizo 5e (year-old car), Arrizo 7E, Tiggo 3xe, a total of 4 models;
- 4.Added Chery and Link Car (Karry, Riich, Rely, Chery_EV), anti-theft, gearbox matching, brake exhaust, vehicle maintenance function reset, EPB initialization, writing VIN code, 5 models Special functions such as tooth learning;
5. Added the automatic positioning function of each car.

Riich V3.50 upgrade Notice

1. Added Chery: Arrizo EX/GX, Tiggo 5x (T19), Tiggo 8 a total of 3 models;
2. Added Karry: K50 electric vehicle (Q26EV), K60 2018 model, K60 country five 1.5T model, K60EV, Q22LEV electric vehicle (Zhongbo) / Youyou EV, Q22LEV electric vehicle (autonomous) a total of 6 models;
3. Added Chery_EV: S32EV, Arrizo 5e (year-old car), Arrizo 7E, Tiggo 3xe, a total of 4 models;
- 4.Added Chery and Link Car (Karry, Riich, Rely, Chery_EV), anti-theft, gearbox matching, brake exhaust, vehicle maintenance function reset, EPB initialization, writing VIN code, 5 models Special functions such as tooth learning;
5. Added the automatic positioning function of each car.

SGMW V3.75 upgrade Notice

- 1.Solve the problem that the Wuling Hongguang SRS fault code is not defined in 2012;
- 2.Solve the problem of occasional crash when one-button scanning of Chevrolet Lechi, Wulingzhi and other models;
- 3.Solve the problem that 2015 Wuling Hongguang S power steering system version information is not supported;
- 4.Solve the problem that 2015 Wuling Hongguang S1 anti-lock control system action test does not support;
- 5.Solve the problem that the Wuling Hongguang Engine control system action test prompt text is abnormal in 2014.

Emgrand V4.00 upgrade Notice

- 1.A total of four models including Geely Automobile, Englon, Gleagle and SMA will be used as the Emgrand Auto Link.
- 2.New support for Emgrand Auto: Borui (Bray GE), Binyue, Binrui, Emgrand Gse, Emgrand GL (Emgrand GL_PHEV, Emgrand GL_14T, Emgrand GL_15TD), the new Emgrand PHEV a total of 8 models.
- 3.Added 211 special functions such as VIN code, tooth learning, one-button configuration,

gearbox matching, brake exhaust, etc. for Emgrand, Geely, Englon, Gleagle and SMA.
4.Added support for precise automatic positioning of Emgrand, Geely, Englon and Gleagle.

Geely V4.00 upgrade Notice

- 1.A total of four models including Geely Automobile, Englon, Gleagle and SMA will be used as the Emgrand Auto Link.
- 2.New support for Emgrand Auto: Borui (Bray GE), Binyue, Binrui, Emgrand Gse, Emgrand GL (Emgrand GL_PHEV, Emgrand GL_14T, Emgrand GL_15TD), the new Emgrand PHEV a total of 8 models.
- 3.Added 211 special functions such as VIN code, tooth learning, one-button configuration, gearbox matching, brake exhaust, etc. for Emgrand, Geely, Englon, Gleagle and SMA.
- 4.Added support for precise automatic positioning of Emgrand, Geely, Englon and Gleagle.

Englon V4.00 upgrade Notice

- 1.A total of four models including Geely Automobile, Englon, Gleagle and SMA will be used as the Emgrand Auto Link.
- 2.New support for Emgrand Auto: Borui (Bray GE), Binyue, Binrui, Emgrand Gse, Emgrand GL (Emgrand GL_PHEV, Emgrand GL_14T, Emgrand GL_15TD), the new Emgrand PHEV a total of 8 models.
- 3.Added 211 special functions such as VIN code, tooth learning, one-button configuration, gearbox matching, brake exhaust, etc. for Emgrand, Geely, Englon, Gleagle and SMA.
- 4.Added support for precise automatic positioning of Emgrand, Geely, Englon and Gleagle.

Gleagle V4.00 upgrade Notice

- 1.A total of four models including Geely Automobile, Englon, Gleagle and SMA will be used as the Emgrand Auto Link.
- 2.New support for Emgrand Auto: Borui (Bray GE), Binyue, Binrui, Emgrand Gse, Emgrand GL (Emgrand GL_PHEV, Emgrand GL_14T, Emgrand GL_15TD), the new Emgrand PHEV a total of 8 models.
- 3.Added 211 special functions such as VIN code, tooth learning, one-button configuration, gearbox matching, brake exhaust, etc. for Emgrand, Geely, Englon, Gleagle and SMA.
- 4.Added support for precise automatic positioning of Emgrand, Geely, Englon and Gleagle.

SMA V4.00 upgrade Notice

- 1.A total of four models including Geely Automobile, Englon, Gleagle and SMA will be used as the Emgrand Auto Link.
- 2.New support for Emgrand Auto: Borui (Bray GE), Binyue, Binrui, Emgrand Gse, Emgrand GL (Emgrand GL_PHEV, Emgrand GL_14T, Emgrand GL_15TD), the new Emgrand PHEV a total of 8 models.
- 3.Added 211 special functions such as VIN code, tooth learning, one-button configuration, gearbox matching, brake exhaust, etc. for Emgrand, Geely, Englon, Gleagle and SMA.
- 4.Added support for precise automatic positioning of Emgrand, Geely, Englon and Gleagle.

Eobd V2.80 upgrade Notice

1. Solve the problem that the engine control system data flow fuel pipe temperature value is wrong.
2. Resolve the 2012 Faw Volkswagen Eobd scan out the KWP2000 protocol, click to enter the failure, exit and then enter Eobd normal problem.
3. Solve the problem of English description in some Chinese fault codes.

ChangAn V2.95 upgrade Notice

1. Added steering angle system for some models such as CS15, CS35, CS75, etc., and added corresponding special functions: steering.
2. Solve the problem that the 2017 Changan Lingxuan electronic stability system, airbag system, power steering system and automatic air conditioning system fault code are not defined.
3. Solve the problem that the 2013 Changan Automobile Starlight 4500 power steering system can't get in.

Peugeot V4.00 upgrade Notice

1. Re-develop the model to support the reading and clearing function of the model in 2018.
2. Solve the problem that the Peugeot 307 parking aid communication failed in 2005 and the SRS fault code is not defined.
3. Optimize the problem that the one-button scanning system cannot be accurately positioned.

Citroen V4.00 upgrade Notice

1. Re-develop the model to support the reading and clearing function of the model in 2018.
2. Solve the problem that the fault code of the Citroen C6 engine control system in 2008 is not defined.
3. Optimize the problem that the one-button scanning system cannot be accurately positioned.

Porsche V3.63 upgrade Notice

1. Solve the problem of unstable Porsche Cayenne ABS communication in 2010.
2. Solve the problem of blank information of the Porsche Cayenne traction board control system, instrument panel control system and reversing auxiliary control system in 2004.

Vw V3.94 upgrade Notice

1. Solve the problem of inaccurate positioning of the vehicle.
2. Solve the problem of brushing the hidden Skoda wilderness expert mode forced exit.

Skoda V3.94 upgrade Notice

1. Solve the problem of inaccurate positioning of the vehicle.
2. Solve the problem of brushing the hidden Skoda wilderness expert mode forced exit.

Seat V3.94 upgrade Notice

1. Solve the problem of inaccurate positioning of the vehicle.
2. Solve the problem of brushing the hidden Skoda wilderness expert mode forced exit.

Lamborghini V3.94 upgrade Notice

1. Solve the problem of inaccurate positioning of the vehicle.
2. Solve the problem of brushing the hidden Skoda wilderness expert mode forced exit.

Bugatti V3.94upgrade Notice

- 1.Solve the problem of inaccurate positioning of the vehicle.
- 2.Solve the problem of brushing the hidden Skoda wilderness expert mode forced exit.

Bentley V3.94upgrade Notice

- 1.Solve the problem of inaccurate positioning of the vehicle.
- 2.Solve the problem of brushing the hidden Skoda wilderness expert mode forced exit.

Audi V3.94upgrade Notice

- 1.Solve the problem of inaccurate positioning of the vehicle.
- 2.Solve the problem of brushing the hidden Skoda wilderness expert mode forced exit.

Vw CV V3.94upgrade Notice

- 1.Solve the problem of inaccurate positioning of the vehicle.
- 2.Solve the problem of brushing the hidden Skoda wilderness expert mode forced exit.

Maintenance Function Upgrade Instructions In August

Oil Service V2.65 upgrade Notice

1. Optimized Mercedes Benz C200, LandRover Freelander, Mercedes Benz GLA200, BMW 420i, BMW 325i, BMW X1, Ferrari F12, Mercedes Benz CLA260, JMC Transit, Mercedes Benz CLK280, Lexus, MINI, Ford Explorer oil reset function.
2. Added supports for Chevrolet Equinox, Karry Q26(K50)AT, Audi S4 oil reset function
3. Added supports for Emgrand Borui, Binyue, Binrui, Emgrand GSE, Emgrand PHEV, New vision 2018 oil reset function
4. Added supports for Baic BJ40, Senova Zhidao, Weiwang M50F, Weiwang M60 etc. Total 10 models oil reset function.
5. Added Cherry QQ3 series, Cowin2/Cowin series, Eastar Cross series,Arrizo EX oil reset function.
6. Added supports for DFPV A30, A60, AX4, AX5, AX3 oil reset function.
7. Added supports for Changan CS35(PLUS), CE15_EV, CS15_EV_ICA oil reset function.
8. Added supports for ZOTYE T200, T800, Z300EV oil reset function.
9. Added supports for Refine S3 Gen 3, Refine S5 oil reset function.
10. Added supports for Karry Youyi series(A18/Karry 3), QQ3 series, Q26(K50)AT, K60 National V emission standard 1.5T, K60 2018 oil reset function.

Throttle Reset V2.82 upgrade Notice

1. Added support for Emgrand GS, GL, EC713 throttle matching.
2. Added support for 2002-2006 years Kia Sorento throttle matching.
3. Added support for 2018 years Baojun 360 throttle matching.
4. Added support for 2009 years Chevrolet Captiva throttle matching.
5. Added support for Bentley throttle matching.
6. Optimize ZxAuto, Audi, Chery, Great Wall H6, Honda Stream, Porsche Cayenne, BMW, Chery Qiyun 2, Land Rover, Renault Koleos, Chevrolet, Cadillac XT5, Tianjin FAW, Ford, Volvo XC90, Hyundai Sonata(NFC), Kia Optima(TF) throttle matching.

Summary of other upgrades in August

T6 &T6PRO VCI FirmWare V3.15 upgrade Notice

1. Add interface support for setting ISO15765_BS and ISO15765_STmin when

- Communication Parallel Links Greater than 1 for Benz DTS Original adaptation.
2. Add support for Extend Address CAN filter for Porsche Original adaptation.
 3. Discard the received original CAN message when receiving a data frame of ISO15765_2 above the long frame data (3K) If CAN_MIXED_FORMAT is enabled
 4. Fix bug that Sending data is wrong for CAN Protocol and Optimize The Reception Timestamp for Raw CAN Protocol.

T3 VCI FirmWare V2.95 upgrade Notice

1. Solve the problem of water chestnut airbag.
2. PWM protocol optimization.

wiScan Tool V3.26 upgrade Notice

1. Fixed the problem of V3.25 version that could not detect the latest firmware.

wiScan T6 Benz V2.28 upgrade Notice

1. Add Support for DTS and Vediamo.