



Dear Sirs,

Thank you for your interest in our product.

The DIGA-Consult is the most complete available programming device for digital speedometers. The system is a high-quality tool, which offers a maximum of flexibility and working comfort despite simple operation.

Outstanding characteristics of the system are:

- The current odometer reading is decoded and indicated.
- Intuitive operability by clear menu guidance.
- Light display.
- Menu guidance in different languages (D, E, F, I, ESP, POL, ....)
- All data can be edited, stored and loaded.
- The stored data can be transferred to a PC for archiving.
- Defective speedometers can be comfortably repaired.
- You can download developed software directly through our internet server.
- New types and marks can be de-energised within seconds by telephone.
- The annoying post office dispatch of the equipment is void.

With purchase a briefing and a constant telephone support are natural for questions and problems by us.

The prices for the different versions are:

Version 1: 6,000,- euro + 19% tax

Version 2: 9,000,- euro + 19% tax (+ our hotair-soldering station DIGA-Station for free)

BMW-Upgrade: 2,500,- euro + 19% tax

(19% tax: except EC consignees with sales tax ID no. or export to a non-member country)

These versions you can supplement at will with other models.

Contained in each case are the DIGA-Consult, all necessary plugs, cable, guidances (detailed CD Rom with guidance for all models), special tools, etc... Further we stand for our customers always for questions for order, both by E-Mail and by telephone.

If you should wish an individual software package, communicate to us please, which models you need and we create you an offer.

I hope, this offer is interesting to you. For further questions please contact me.

Yours sincerely,

The DIGA-Consult: Each package contains the Diga-Consult, all necessary plugs, cables, guidances (cd-rom with manuals for all models)



Also have a look at our other products for odometer programming specialists:

The DIGA-Station: Our HotAir-Soldering station especially for SMD-work on clusters



new products like the DIGA-Counter for solving the problems for the programming of the Renault Sagem - clusters are in progress and will be released soon!

## References to the DIGA-Consult – Modelist:

**Diagnosis-plug:** programming is made in few seconds by the Diagnosis-Plug interface of the vehicle

**Cluster-plug:** the removed cluster is connected and programmed with the DIGA-Consult

**Directly:** the Cluster must be removed and opened for programming. Partly soldering work is necessary.

**Version 1** is the basic version.

With it the most usual vehicles can be programmed. Ideally for newbies.

**Version 2** is suitable for the professional.

Here also exotic cars are contained, with which soldering work on the processor is contained.

**BMW-Upgrade** is suitable for the BMW professional.

The hard and software for the treatment of the BMW keys and light modules.

The BMW-Upgrade is functions only in connection with a DIGA-Consult handheld.

### **Programming techniques:**

<b>diagnosis-plug:</b>	programming without removing the cluster
<b>cluster-plug:</b>	programming without opening the cluster
<b>eprom:</b>	programming the eeprom by clip
<b>soldering contacts:</b>	programming by soldering contacts on the circuit board
<b>processor:</b>	processor direct programming

Manufacturer	Model	Version	Method	V1	V2	
Aprilia	RSV	100-pin	Processor			
	Falco	100-pin	Processor			
	Racing 125		Eeprom			
	SR Factory		Eeprom			
	Scarabeo		Eeprom			
	Scarabeo 500	Modell 2004-	Eeprom			
Alfa Romeo	145	old	Processor			
		new	Processor			
	146	old	Processor			
		new	Processor			
	147		Eeprom			
	147		NEC-Processor			
	156	before 2002	Cluster-Plug			
		since 2002	Cluster-Plug			
	159		Eeprom			
	166		Processor			
		Model 2002	Eeprom			
	Spider		Processor			
	GT		Eeprom			
	GTV		Processor			
		All JTD (Diesel) Motor-Control Unit		Eeprom		
		All JTD (Diesel) Motor-Control Unit	New Version	Eeprom		
Aston Martin	DB7		Processor			
	DB9		Processor			
Audi	A2	VDO	Eeprom			
		VDO	Cluster-Plug			
		VDO	Diagnosis-Plug			
		VDO Model 2002	Eeprom			
		VDO Model 2002	Diagnosis-Plug			
	A3/S3	VDO	Eeprom			
		VDO	Diagnosis-Plug			
		UKNSI	Eeprom			
		VDO since 2000	Eeprom			
		VDO ab2000	Cluster-Plug			
		VDO since 2000	Diagnosis-Plug			
		Jaeger before 6/2001	Cluster-Plug			
		Jaeger before 6/2001	Cluster-Plug			
		Jaeger since 7/2001	Cluster-Plug			
		Jaeger	Diagnosis-Plug			
		VDO Model 2002	Eeprom			
		VDO Model 2002	Diagnosis-Plug			
		VDO Modell 2005	Diagnosis-Plug			
		A4/S4	VDO old	direkt		

		VDO old	Diagnosis-Plug		
		VDO old MFA	Eeprom		
		VDO old MFA Version 1	Diagnosis-Plug		
		VDO old MFA Version 2	Diagnosis-Plug		
		VDO new	Eeprom		
		VDO new	Diagnosis-Plug		
		UKNSI old	Eeprom		
		UKNSI new	Eeprom		
		UKNSI 2 Eeproms	Eeprom		
		VDO since 2000	Eeprom		
		VDO since 2000	Cluster-Plug		
		VDO since 2000	Diagnosis-Plug		
		Jaeger	Cluster-Plug		
		Jaeger before 6/2001	Cluster-Plug		
		Jaeger	Diagnosis-Plug		
		Bosch 2001	Eeprom		
		Bosch 2001	Diagnosis-Plug		
		Bosch 2002	Eeprom		
		Bosch 1/01-9/01	Diagnosis-Plug (Fast search)		
	<b>A6/S6</b>	VDO old	Eeprom		
		VDO old	Diagnosis-Plug		
		VDO new	Eeprom		
		VDO new	Diagnosis-Plug		
		VDO since 2000	Eeprom		
		VDO since 2000	Cluster-Plug		
		VDO since 2000	Diagnosis-Plug		
		Jaeger before 6/2001	Cluster-Plug		
		Jaeger before 6/2001	Cluster-Plug		
		Jaeger since 7/2001	Cluster-Plug		
		Jaeger	Diagnosis-Plug		
		VDO Model 2002	Eeprom		
		VDO Model 2002	Diagnosis-Plug		
		Magnetti-Marelli model 2005	Diagnosis-Plug		
	<b>A8/S8</b>	VDO Version 1	Eeprom		
		VDO Version 1	Diagnosis-Plug		
		VDO Version 2	Eeprom		
		VDO Version 2	Diagnosis-Plug		
		VDO since 1999 Version 1	Eeprom		
		VDO since 1999 Version 2	Eeprom		
		VDO model 2005	Diagnosis-Plug		
	<b>TT</b>	Jaeger	Diagnosis-Plug		
		Jaeger since 2000	Cluster-Plug		
		Jaeger before 6/2001	Cluster-Plug		
		Jaeger since 7/2001	Cluster-Plug		
		Jaeger since 2000	Diagnosis-Plug		

	<b>Service-Display</b>	all models	Diagnosis-Plug		
	<b>TV-Unlocking</b>		Manual		
<b>Bentley</b>	<b>GT</b>		Eeprom		
<b>Benelli</b>	<b>Benelli Tornado</b>		Eeprom		
	<b>TNT</b>		Eeprom		
<b>BMW</b>	<b>3er E36</b>	before SW 23	Diagnosis-Plug		
		SW 24	Cluster-Plug		
	<b>3er E36 Compact</b>	SW 20	Cluster-Plug		
		SW 6+7	Cluster-Plug		
		SW 9+10	Eeprom		
		SW 9+10	Cluster-Plug		
	<b>3er E46</b>	before SW 16	Eeprom		
		before SW 16	Diagnosis-Plug		
		Service-Display	Eeprom		
		since SW 17 without eeprom replacing	Soldering contacts		
	<b>1er E87</b>	Cluster	Eeprom		
	<b>1er E87</b>	CAS	Cluster-Plug		
	<b>3er E90</b>	Cluster	Eeprom		
	<b>3er E90</b>	CAS	Cluster-Plug		
	<b>5er E34</b>	Codeplug brown	Eeprom		
		Codeplug blue	Eeprom		
		Codeplug green	Eeprom		
	<b>5er E39</b>	low	Eeprom		
		low	Diagnosis-Plug		
		low SW 15	Diagnosis-Plug		
		low SW 16	Diagnosis-Plug		
		low since SW 17 without eeprom replacing	Soldering contacts		
		high + IKE	Eeprom		
		high + IKE	Diagnosis-Plug		
		high - IKE	Cluster-Plug		
		high – IKE SW 13	Soldering contacts		
		high – IKE since SW 14 without eeprom replacing	Soldering contacts		
	<b>5er E60</b>	Cluster	Eeprom		
	<b>5er E60</b>	CAS	Cluster-Plug		
	<b>5er E61</b>	Cluster	Eeprom		
	<b>5er E61</b>	CAS	Cluster-Plug		
	<b>6er E63 (Coupe)</b>	Cluster	Eeprom		
	<b>6er E63 (Coupe)</b>	CAS	Cluster-Plug		
	<b>6er E64 (Cabrio)</b>	Cluster	Eeprom		
	<b>6er E64 (Cabrio)</b>	CAS	Cluster-Plug		

	<b>7er E32</b>	Codeplug brown	Eeprom		
		Codeplug blue	Eeprom		
		Codeplug green	Eeprom		
	<b>7er E38</b>	low	Eeprom		
		low	Diagnosis-Plug		
		low SW 15	Diagnosis-Plug		
		low SW 16	Diagnosis-Plug		
		low since SW 17 without eeprom replacing	Soldering contacts		
		high + IKE	Eeprom		
		high + IKE	Diagnosis-Plug		
		high - IKE	Cluster-Plug		
		high – IKE SW 13	Soldering contacts		
		high – IKE since SW 14 without eeprom replacing	Soldering contacts		
	<b>7er E65</b>	CAS	CAS Diagnosis-Plug		
	<b>7er E65</b>	Fehlerspeicher	CAS Diagnosis-Plug		
	<b>7er E65 (Facelift)</b>	Cluster	Eeprom		
	<b>7er E65 (Facelift)</b>	CAS	Cluster-Plug		
	<b>7er E66 (Long Version)</b>	Cluster	Eeprom		
	<b>7er E66 (Long Version)</b>	CAS	Cluster-Plug		
	<b>8er E31</b>		Eeprom		
			Diagnosis-Plug		
	<b>Z3</b>	SW 20	Cluster-Plug		
		SW 6+7	Cluster-Plug		
		SW 9+10	Eeprom		
		SW 9+10	Cluster-Plug		
	<b>X3</b>		Eeprom		
	<b>X5</b>	high – IKE SW 13	Soldering contacts		
		high – IKE since SW 14 without eeprom replacing	Soldering contacts		
	<b>Z8</b>		Eeprom		
	<b>TV-Unlocking</b>	MK I + MK II (before 1999)	Manual		
		MK III (since 2000)	Diagnosis-Plug		
	<b>F650 GS</b>		Eeprom		
	<b>C1</b>		Eeprom		
	<b>Service-Programming</b>	<b>After 2001 with OBD II</b>	Diagnosis		
<b>Citroen</b>	<b>Xsara</b>		Eeprom		
	<b>Xsara</b>	After model 2000	NEC-Hardware		
	<b>Xsara</b>	After model 2003	Eeprom		
	<b>Xsantia</b>		Eeprom		
	<b>Berlingo</b>	To 2003 cluster + BSI	Eeprom		
	<b>Berlingo</b>	2003 cluster + BSI	Eeprom		
	<b>C2</b>	To 2004 cluster + BSI	Eeprom		

	<b>C2</b>	After 2004 cluster + BSI	Eeprom		
	<b>C3</b>		Eeprom		
	<b>C4</b>		Eeprom		
	<b>C5</b>	Model 2001 BSI	Soldering contacts		
	<b>C5</b>	Model 2002 cluster + BSI	Soldering contacts		
	<b>C5</b>	BSI Valeo	Eeprom		
	<b>C5</b>	BSI Valeo New Version	Eeprom		
	<b>C5</b>	New Version 2	Soldering-Contacts		
	<b>C5</b>	New Version 3	Soldering-Contacts		
	<b>C5</b>	New Version 4	Soldering-Contacts		
	<b>C5</b>	New Version 5	Soldering-Contacts		
	<b>C8</b>	3 modules	Eeprom + Soldering contacts		
	<b>Dispatch</b>		Processor		
	<b>Evasion</b>		Processor		
	<b>Jumper</b>		Eeprom		
	<b>Jumpy</b>	V1	Processor		
		V2	Processor		
	<b>Picasso</b>	To modell 2004 BSI	NEC-Hardware		
		2004 cluster + BSI	Eeprom		
	<b>Saxo</b>		Cluster-Plug		
	<b>Synergie</b>		Processor		
	<b>Relay</b>		Eeprom		
<b>Cagiva</b>	<b>Raptor</b>		Eeprom		
<b>Chrysler</b>	<b>Cherokee</b>		Diagnosis		
		Model 2002	Diagnosis		
		Model 2003	Diagnosis		
	<b>Crossfire</b>		Diagnosis		
	<b>Grand Cherokee</b>	before 3/1999	Diagnosis		
		4/1999 - 2002	Cluster-Plug		
		since 2002 (912)	Diagnosis		
	<b>Grand Cherokee</b>	Modell 2005	Eeprom		
	<b>Liberty</b>		Diagnosis		
	<b>Neon</b>		Diagnosis		
	<b>PT Cruiser</b>		Diagnosis		
		Model 2002 (912)	Diagnosis		
	<b>Stratus</b>	before 1999	Diagnosis		
		since 1999	Diagnosis		
	<b>Wrangler</b>		Diagnosis		
	<b>Voyager</b>	before 1999	Diagnosis		
		since 1999	Diagnosis		
		Model 2002 (912)	Diagnosis		
	<b>300C</b>		Processor		
	<b>SRI-Speicher</b>	all models	Diagnosis		
<b>Daewoo</b>	<b>Lancetti</b>		Eeprom		



	<b>Nubira</b>		Eeprom		
<b>Daihatsu</b>	<b>YRV</b>		Eeprom		
	<b>Terios</b>		Eeprom		
<b>Ducati</b>	<b>749</b>		Eeprom		
	<b>Monster</b>		Eeprom		
<b>Ferrari</b>	<b>360 Modena</b>		Eeprom		
	<b>550 Maranello</b>		Eeprom		
	<b>F430</b>		Eeprom		
<b>Fiat</b>	<b>Brava</b>	ST	Processor		
		Custom	Processor		
		908 Version 1	Processor		
		908 Version 2	Processor		
		UKNSI	Eeprom		
	<b>Bravo</b>	ST	Processor		
		Custom	Processor		
		908 Version 1	Processor		
		908 Version 2	Processor		
		UKNSI	Eeprom		
	<b>Doblo</b>	Version 1	Processor		
		Version 2	Processor		
		NEC	Eeprom		
		2004	Eeprom		
	<b>Ducato</b>	Nec 2002	Eeprom		
	<b>Idea</b>		Eeprom		
	<b>Idea Multijet</b>		Eeprom		
	<b>Marea</b>	MM3S	Processor		
		C(QAF/OPT)	Processor		
		P(68H)	Processor		
	<b>Multipla</b>		Eeprom		
		Model 2002	Eeprom		
2004	<b>Palio</b>	Version 1	Processor		
by		Version 2	Processor		
	<b>Panda</b>		Eeprom		
	<b>Panda Multijet</b>		Eeprom		
DIGA-Soft.de	<b>Punto</b>	2000 Version 1	Soldering contacts		
		2000 Version 2	Soldering contacts		
		2000 Version 3	Soldering contacts		
		2001 Version 1	Soldering contacts		
		2001 Version 2	Soldering contacts		
2004		2001 Version 3	Soldering contacts		
		2002 Nec	Eeprom		
		2003 Nec	Eeprom		
		CAN	Cluster-Plug		
	<b>Punto Multijet</b>		Eeprom		
by	<b>Scudo</b>	Version 1	Processor		
DIGA-Soft.de		Version 2	Processor		
	<b>Seicento</b>	NEC	Processor		
	<b>Stilo</b>	912	Soldering contacts		

	<b>Strada</b>		Eeprom		
	<b>Tempra</b>	Tempra	Eeprom		
		Borg	Eeprom		
		Veglia	Eeprom		
	<b>Tipo</b>	Borg	Eeprom		
		Veglia	Eeprom		
	<b>Ulysse</b>		Processor		
	<b>Ulysee</b>	2004 - 3 modules	Eeprom/Soldering contacts		
	<b>All JTD (Diesel) Motor-Control Unit</b>		Eeprom		
	<b>All JTD (Diesel) Motor-Control Unit</b>	New Version	Eeprom		
<b>Ford</b>	<b>C-Max</b>		Processor		
	<b>C-Max</b>	Modell 2005	Processor		
	<b>Cougar</b>		Processor		
	<b>Connect</b>		Soldering contacts		
	<b>Escort</b>	Version 1	Soldering contacts		
		Version 2	Soldering contacts		
	<b>Fiesta</b>	Version 1	Soldering contacts		
2004		Version 2	Soldering contacts		
		Model 2002	Eeprom		
	<b>Fiesta</b>	<b>Model 2006</b>	<b>Processor (9S12)</b>		
	<b>Ka</b>		NEC-Hardware		
by	<b>Focus</b>	Version 1	Cluster-Plug		
DIGA-Soft.de		Version 2	Cluster-Plug		
		Model 2003	Eeprom		
	<b>Focus</b>	Modell 2005	Processor		
	<b>Focus RS</b>		Soldering contacts		
	<b>Fusion</b>		Eeprom		
	<b>Galaxy</b>	before Model 2001	Diagnosis-Plug		
		since Model 2001 Version 1	Eeprom		
		since Model 2001 Version 2	Eeprom		
2004		since Model 2001 Version 1+2	Diagnosis-Plug		
		since Model 2002	Diagnosis-Plug		
	<b>Maverick</b>		Processor		
by	<b>Mondeo</b>		Soldering contacts		
DIGA-Soft.de	<b>Puma</b>		Soldering contacts		
	<b>Ranger</b>		Soldering contacts		
	<b>Ranger</b>	<b>Model 2005</b>	<b>Processor (9S12)</b>		
	<b>Scorpio</b>		Cluster-Plug		
	<b>Transit</b>	-2003	Eeprom		
		2003	Eeprom		
<b>GMC</b>	<b>Seville STS</b>		Eeprom		
<b>Harley-Davidson &amp; Buell</b>	<b>All models</b>	Up to Model 2001	Eeprom		

	<b>All models</b>	from Model 2002	Eeprom		
	<b>Fatboy</b>		Eeprom		
	<b>Buell Firebolt</b>		Eeprom		
<b>Hyundai</b>	<b>Santa Fe</b>	Version 1	Eeprom		
		Version 2	Eeprom		
			NEC-Hardware		
	<b>Coupe</b>		Eeprom		
	<b>Getz</b>		Eeprom		
	<b>Accent</b>		Eeprom		
	<b>Matrix</b>		Eeprom		
	<b>XG 30</b>		Eeprom		
	<b>Terracan</b>		NEC-Hardware		
	<b>Elantra</b>		NEC-Hardware		
	<b>Elantra</b>		<b>Eeprom</b>		
	<b>Tuscan</b>		Eeprom		
<b>Honda</b>	<b>Accord</b>		Eeprom		
		705 Processor	Processor		
		2003	Soldering contacts		
	<b>Element</b>		<b>Eeprom</b>		
	<b>Civic</b>		Eeprom		
	<b>Civic</b>	After Modell 2004	Eeprom		
	<b>CRV</b>		Eeprom		
	<b>CRV</b>	Modell 2002 to Modell 2004	Eeprom		
	<b>CRV</b>	After Modell 2005	Eeprom		
	<b>CBR 600</b>	After Modell 2003	Eeprom		
	<b>CBR 900 Fireblade</b>	To Modell 2006	Eeprom		
	<b>CBR 900 Fireblade</b>	<b>Modell 2006-</b>	<b>Eeprom</b>		
	<b>Goldwing</b>		Eeprom		
2004	<b>HRV</b>		Eeprom		
	<b>Jazz</b>		Eeprom		
	<b>Jazz</b>	After Modell 2004	Eeprom		
By	<b>Legend</b>		Eeprom		
DIGA-Soft.de	<b>Logo</b>		Eeprom		
	<b>Shuttle</b>		Eeprom		
	<b>Stream</b>		Eeprom		
	<b>S2000</b>		Eeprom		
	<b>SV650</b>	<b>Modell 2005-</b>	<b>Eeprom</b>		
	<b>Hornet</b>		Eeprom		
	<b>Varadero</b>		Eeprom		
	<b>VFR 800</b>		Eeprom		
		Model 2004	Eeprom		
	<b>VFR 1000</b>		Eeprom		
	<b>VT 1100</b>		Eeprom		
<b>Isuzu</b>	<b>Rodeo</b>		Eeprom		
	<b>Trooper</b>		Eeprom		
	<b>Pickup</b>		Eeprom		

<b>Iveco</b>	<b>Daily</b>		Eeprom		
<b>Jaguar</b>	<b>Daimler/XJ</b>	11DU Version 1	Cluster-Plug		
		11DU Version 2	Cluster-Plug		
2004		11DU Version 3	Cluster-Plug		
by	<b>XK8</b>	before 2000	Soldering contacts		
DIGA-Soft.de		since 2000	Soldering contacts		
		since 2003	Processor		
	<b>X-Type</b>	Version 1	Soldering contacts		
		Version 2	Soldering contacts		
	<b>S-Type</b>				
		Model 2003	Processor		
	<b>S-Type</b>	After Modell 2004	Eeprom		
<b>Kawasaki</b>	<b>GPZ 600</b>		Eeprom		
	<b>KVF 650</b>		Eeprom		
	<b>ZX 6</b>		Eeprom		
	<b>ZX 6R</b>		Eeprom		
		2003	Eeprom		
	<b>ZXR 6R 636</b>		Eeprom		
	<b>ZX 9</b>		Eeprom		
	<b>ZX 9R</b>		Eeprom		
	<b>ZX 12R</b>		Eeprom		
<b>Kia</b>	<b>Carens</b>		Eeprom		
	<b>Carnival</b>		Eeprom		
	<b>Cerato</b>		Eeprom		
	<b>Picanto</b>		Eeprom		
	<b>Rio</b>		Eeprom		
	<b>Rio</b>		Eeprom		
	<b>Sportage</b>		Eeprom		
	<b>Sorento</b>		Eeprom		
<b>Lamborghini</b>	<b>Gallardo</b>		Eeprom		
	<b>Diablo</b>	Model 1999 to Model 2001	Eeprom		
	<b>Murcielago</b>		Eeprom		
<b>Lancia</b>	<b>Kappa</b>		Soldering contacts		
	<b>Lybra</b>	Version 1	Soldering contacts		
		Version 2	Soldering contacts		
2004		Version 3	Soldering contacts		
	<b>Thesis</b>		Eeprom		
	<b>Musa</b>		Eeprom		
by	<b>Y</b>	Version 1	Soldering contacts		
DIGA-Soft.de		Version 2	Soldering contacts		
		Version 3	Soldering contacts		
		Version 4	Processor		
		Version 5 SC51 Processor	Processor		
	<b>All JTD (Diesel) Motor-Control</b>		Eeprom		

	<b>Unit</b>				
	<b>All JTD (Diesel) Motor-Control Unit</b>	New Version	Eeprom		
<b>Lexus</b>	<b>GS 300</b>		Eeprom		
	<b>Harrier Jeep</b>		Eeprom		
2004	<b>IS 200</b>		Eeprom		
by	<b>LS 200</b>		Eeprom		
DIGA-Soft.de	<b>LS 300</b>		Eeprom		
	<b>LS 400</b>		Eeprom		
	<b>LX 470</b>		Eeprom		
		Model 2002	Eeprom		
	<b>RX 300</b>		Eeprom		
	<b>SC 400</b>		Eeprom		
<b>Landrover</b>	<b>Defender</b>		Eeprom		
	<b>Discovery</b>	before 6/2001	Processor		
		since 6/2001	Processor		
	<b>Discovery TD6</b>	After Modell 2005	Eeprom		
	<b>Freelander</b>	UKNSI+C567	Eeprom		
		VDO 2002	Eeprom		
	<b>Range Rover</b>	Model 2002	Eeprom		
	<b>Range Rover Sport</b>	After Modell 2005	Eeprom		
	<b>TD 5</b>	before 6/2001	Processor		
		since 6/2001	Processor		
<b>Lotus</b>	<b>Elise</b>		Eeprom		
	<b>Esprit</b>		Eeprom		
<b>Lincoln</b>	<b>Towncar</b>		Processor	Auf Anfrage	
		1995	Processor		
		before 1999	Processor		
		since 1999	Processor		
<b>Maserati</b>	<b>Quattroporte</b>		Eeprom		
<b>MAN</b>	<b>Truck</b>	without tachograph	Eeprom		
<b>Mazda</b>	<b>121</b>		Eeprom		
	<b>2</b>		Eeprom		
	<b>323</b>	Version 1	Eeprom		
		Version 2	Eeprom		
		Version 3	Eeprom		
	<b>3</b>		Eeprom		
	<b>626</b>	Version 1	Eeprom		
2004		Version 2	Eeprom		
by		Version 3	Eeprom		
	<b>6</b>		Eeprom		
	<b>Demio</b>		Eeprom		
DIGA-Soft.de	<b>E2200</b>		Eeprom		

	<b>MPV</b>		Eeprom		
	<b>MX 5</b>		Eeprom		
	<b>Pickup B2500</b>		Eeprom		
	<b>Premacy</b>		Eeprom		
	<b>RX-8</b>		Eeprom		
	<b>Tribute</b>		Processor		
	<b>Tribute</b>		Processor (9S12)		
	<b>Xedos 9</b>		Eeprom		
<b>Mercedes</b>	<b>A-Klasse</b>	before Model 2000	Diagnosis-Plug		
		since Model 2000	Cluster-Plug		
		since Model 2000	Diagnosis-Plug		
	<b>C-Klasse (W202)</b>	VDO – 9/1995	Eeprom		
2004		VDO -9/1995	Cluster-Plug		
by		MotoMeter – 9/1995	Eeprom		
DIGA-Soft.de		MotoMeter – 9/1995	Cluster-Plug		
		9/1995 -4/1998 Version 1	Eeprom		
		9/1995 -4/1998 Version 2	Eeprom		
		9/1995 -4/1998 Version 1+2	Diagnosis-Plug		
		since 4/1998	Eeprom		
		since 4/1998	Diagnosis-Plug		
	<b>C-Klasse (W203)</b>	Cluster	Eeprom		
		Cluster	Cluster-Plug		
		Ignition lock Version 1	Processor		
		Ignition lock Version2	Processor		
		Ignition lock since 5/2001	Processor		
		Flash cluster	Cluster-Plug		
2004	<b>CL (W140)</b>	before 6/1996	Eeprom		
by		before 6/1996	Cluster-Plug		
DIGA-Soft.de		6/1996 –4/1998 Version 1	Eeprom		
		6/1996 –4/1998 Version 2	Eeprom		
		6/1996 –4/1998 Version 1+2	Diagnosis-Plug		
		since 4/1998	Eeprom		
		since 4/1998	Diagnosis-Plug		
	<b>CL (W215)</b>	before 2000	Eeprom		
		before 5/2001	Eeprom		
2004		Ignition lock since 5/2001 Version 1	Processor		
by		Ignition lock since 5/2001 Version 2	Processor		
		Ignition lock Model 2002	Processor		

DIGA-Soft.de		Service-Display	Eeprom		
	<b>CLK</b>	before 4/1998 Version 1	Eeprom		
		before 4/1998 Version 2	Eeprom		
		before 4/1998 Version 1+2	Diagnosis-Plug		
		4/1998 –7/1999	Eeprom		
		4/1998 –7/1999	Diagnosis-Plug		
2004		since 7/1999	Eeprom		
by		since 7/1999	Diagnosis-Plug		
DIGA-Soft.de	<b>E-Klasse</b>	before 4/1998 Version 1	Eeprom		
		before 4/1998 Version 2	Eeprom		
		before 4/1998 Version 1+2	Diagnosis-Plug		
		4/1998 –7/1999	Eeprom		
		4/1998 –7/1999	Diagnosis-Plug		
		since 7/1999	Eeprom		
		since 7/1999	Diagnosis-Plug		
		W211	Cluster-Plug		
2004	<b>G-Klasse</b>		Eeprom		
by			Diagnosis-Plug		
DIGA-Soft.de	<b>M-Klasse</b>		Eeprom		
			Diagnosis-Plug		
	<b>S-Klasse (W140)</b>	before 6/1996	Eeprom		
		before 6/1996	Cluster-Plug		
		6/1996 –4/1998 Version 1	Eeprom		
		6/1996 –4/1998 Version 2	Eeprom		
		6/1996 –4/1998 Version 1+2	Diagnosis-Plug		
		since 4/1998	Eeprom		
2004		since 4/1998	Diagnosis-Plug		
by	<b>S-Klasse (W220)</b>	before 2000	Eeprom		
DIGA-Soft.de		before 5/2001	Eeprom		
		Ignition lock since 5/2001 Version 1	Processor		
		Ignition lock since 5/2001 Version 2	Processor		
		Ignition lock Model 2002	Processor		
		Service-Display	Eeprom		
	<b>SL (R129)</b>	before 6/1996	Eeprom		
		before 6/1996	Cluster-Plug		
		6/1996 –4/1998 Version 1	Eeprom		
2004		6/1996 –4/1998 Version 2	Eeprom		
by		6/1996 –4/1998 Version 1+2	Diagnosis-Plug		
DIGA-Soft.de		since 4/1998	Eeprom		
		since 4/1998	Diagnosis-Plug		
	<b>SL (R230)</b>	cluster	Eeprom		

		Ignition lock	Processor		
		Ignition lock Model 2002	Processor		
	<b>SLK</b>	before 4/1998 Version 1	Eeprom		
		before 4/1998 Version 2	Eeprom		
		before 4/1998 Version 1+2	Diagnosis-Plug		
2004		since 4/1998	Eeprom		
by		since 4/1998	Diagnosis-Plug		
DIGA-Soft.de	<b>Sprinter</b>	VDO before 1999 Version 1	Eeprom		
		VDO before 1999 Version 2	Eeprom		
		VDO before 1999 Version 1+2	Cluster-Plug		
	Working hours	VDO before 1999	Eeprom		
		VDO since 2000	Eeprom		
		Kienzle before 1999	Eeprom		
			Diagnosis-Plug		
2004		Kienzle since 2000	Eeprom		
DIGA-Soft.de		Magneti Marelli Version 1	Processor		
		Magneti Marelli Version 2	Processor		
		Magneti Marelli	Diagnosis-Plug		
	<b>Vito</b>	VDO before 1999 Version 1	Eeprom Version 1		
		VDO before 1999 Version 2	Eeprom Version 2		
		VDO before 1999 Version 1+2	Cluster-Plug		
	<b>Working Hours</b>	VDO before 1999	Eeprom		
		VDO since 2000	Eeprom		
		Magneti Marelli Version 1	Processor		
		Magneti Marelli Version 2	Processor		
		Magneti Marelli	Diagnosis-Plug		
		2004 cluster + Ignition lock	Eeprom + Soldering contacts		
	<b>Service-Display</b>	all models before 4/1998	Diagnosis-Plug		
		all models since 4/1998	Diagnosis-Plug		
	<b>Trip Since Last Service</b>	W 203 W209 W211	Diagnosis		
<b>Mitsubishi</b>	<b>Spacegear</b>		Eeprom		
		Yazaki	Eeprom		
	<b>Spacewagon</b>		Eeprom		
	<b>Spacestar</b>		Eeprom		
	<b>Spacerunner</b>		Eeprom		
	<b>Charisma</b>		Eeprom		
2004	<b>Colt</b>		Eeprom		
		Model 2004	Eeprom		



by	<b>Lancer</b>		Eeprom		
		Model 2004	Eeprom		
	<b>Outlander</b>		Eeprom		
DIGA-Soft.de	<b>Pajero</b>	Version 1	Eeprom		
		Version 2	Eeprom		
	<b>Pinin</b>		Eeprom		
	<b>Shogun</b>	Version 1	Eeprom		
		Version 2	Eeprom		
<b>MV Agusta</b>	<b>Agusta</b>		Eeprom		
<b>Nissan</b>	<b>Almera</b>	before Model 1999	Eeprom		
		Model 2000 Version 1	Eeprom		
		Model 2000 Version 2	Eeprom		
		Model 2001	Eeprom		
	<b>Cabstar</b>		Soldering contacts		
	<b>Cubic</b>		Eeprom		
	<b>Cubistar</b>		Eeprom		
	<b>Infinity</b>		Eeprom		
	<b>Maxima</b>	before Model 1999	Eeprom		
		since Model 2000	Eeprom		
	<b>Micra</b>	before 2002	Eeprom		
		since 2003	Eeprom		
2004	<b>Primera</b>	before Model 1999	Eeprom		
by		Model 1999	Eeprom		
DIGA-Soft.de		Model 2000	Eeprom		
		Model 2001	Eeprom		
	<b>Patrol</b>		Eeprom		
	<b>Patrol</b>	Modell 2003	Eeprom		
	<b>Pickup</b>		Eeprom		
		Model 2002	Eeprom		
		Model 2003	Eeprom		
	<b>Presage</b>		Eeprom		
	<b>Primastar</b>		Eeprom		
	<b>Nawaro</b>		Eeprom		
	<b>Navara</b>	After Model 2004	Processor		
	<b>Nevada</b>	After Model 2004	Processor		
	<b>Pathfinder</b>	before Model 2000	Eeprom		
		since Model 2000	Eeprom		
	<b>Pathfinder</b>	After Model 2004	Processor		
	<b>Skyline</b>		Eeprom		
	<b>Tino</b>		Eeprom		
	<b>Tino</b>	Modell 2004	Eeprom		
	<b>X-Trail</b>		Eeprom		
	<b>X-Trail</b>	Modell 2004	Eeprom		
	<b>Terrano</b>		Eeprom		
		Model 2002	Eeprom		
	<b>350 ZX</b>		Eeprom		

<b>Opel</b>	<b>Astra</b>	VDO	Eeprom		
		VDO	Diagnosis-Plug		
		VDO Model 2002	Diagnosis-Plug		
		TRW	Eeprom		
		Model 2004	Eeprom		
	<b>Corsa</b>		Diagnosis-Plug		
	<b>Combo</b>		Diagnosis-Plug		
2004	<b>Frontera</b>	VDO	Eeprom		
by		VDO	Diagnosis-Plug		
DIGA-Soft.de		TRW	Eeprom		
		Delco	Eeprom		
	<b>Vectra</b>	VDO before 3/1999	Eeprom		
		VDO before 3/1999	Diagnosis-Plug		
		VDO since 3/1999	Eeprom		
		VDO since 3/1999	Diagnosis-Plug		
		Model 2002	Eeprom		
	<b>Meriva</b>		Diagnosis-Plug		
	<b>Monterey</b>		Eeprom		
	<b>Movano</b>		Eeprom		
	<b>Omega</b>		Eeprom		
	<b>Signum</b>		Eeprom		
	<b>Vivaro</b>		Eeprom		
	<b>Vivaro</b>	Version2	Eeprom		
	<b>Zafira</b>	VDO	Eeprom		
		VDO	Diagnosis-Plug		
		VDO Model 2002	Diagnosis-Plug		
		TRW	Eeprom		
	<b>Zafira</b>	Model 2005	Eeprom		
<b>Peugeot</b>	<b>106</b>		Cluster-Plug		
	<b>206</b>	before 2001	Processor		
		before 2001	Cluster-Plug		
		Service -2001	Cluster-Plug		
		Nec 2002 cluster + BCU	Eeprom		
		Nec 2003 cluster + BCU	Eeprom		
		BCU Autodetect			
	<b>306</b>	Version 1	Eeprom		
		Version 2	Eeprom		
2004	<b>306</b>		Cluster-Plug		
	<b>307</b>	V1	Soldering contacts		
		V2	Soldering contacts		
		V3	Soldering contacts		
		2003	Eeprom		
		From model 2003 cluster	NEC-Hardware		
	<b>307</b>	Model 2006	Eeprom		
by	<b>406</b>	Sagem	Eeprom		
DIGA-Soft.de		Jaeger	Processor		

		VDO Version 1 cluster + BCU	Eeprom		
		VDO Version 2 cluster + BCU	Eeprom		
		VDO Version 3 cluster + BCU	Eeprom		
		BCU 95040	Eeprom		
	<b>607</b>	Tacho + BCU	Eeprom		
			Cluster-Plug		
	<b>806</b>		Processor		
			Cluster-Plug		
	<b>807</b>	3 modules	Eeprom + Soldering contacts		
	<b>807</b>	Version 2	Processor		
	<b>807</b>	Version 3	Processor		
	<b>807</b>	Version 4	Processor		
	<b>807</b>	Version 5	Processor		
	<b>1007</b>		<b>Eeprom</b>		
	<b>Boxer</b>		Eeprom		
	<b>Expert</b>		Processor		
	<b>Partner</b>	to model 2003 BSI	NEC-Hardware		
<b>Porsche</b>	<b>928</b>		Eeprom		
	<b>996</b>	before Model 2000	Eeprom		
		before Model 2000	Diagnosis-Plug		
2004		since Model 2000	Eeprom		
		BCU since 2000	Eeprom		
	<b>997</b>	Model 2005	Eeprom		
by	<b>Boxster</b>	before Model 2000	Eeprom		
DIGA-Soft.de		before Model 2000	Diagnosis-Plug		
		since Model 2000	Eeprom		
	<b>Boxster</b>	Model 2005	Eeprom		
	<b>Cayenne</b>		Eeprom		
	<b>Turbo</b>		Eeprom		
<b>Renault</b>	<b>Avantime</b>	Cluster+BSI	Eeprom+Processor		
	<b>Clio</b>	Sagem before Modell 1999	Eeprom		
		Sagem cluster	NEC-Hardware		
		Sagem 2002 (NEC)	Eeprom		
		Jaeger	Eeprom		
		Jaeger 908	Processor		
		Jaeger 908	Cluster-Plug		
		From model 2004	Eeprom		
	<b>Clio</b>	Model 2005	Processor		
		<b>Modell 2006</b>	<b>Eeprom</b>		
	<b>Dacia</b>		Eeprom		

2004	<b>Espace</b>	since Model 2000 cluster + BCU Version 1	Processor		
by		since Model 2000 cluster + BCU Version 2	Processor		
		2003 V1	Eeprom		
		2003 V2	Eeprom		
		2006	Eeprom		
DIGA-Soft.de	<b>Kangoo</b>		Eeprom		
		908	Processor		
		908	Cluster-Plug		
		since Model 2003	Eeprom		
	<b>Laguna</b>	Sagem	Eeprom		
	<b>Laguna 2001</b>	908	Processor		
		912	Soldering contacts		
	<b>Laguna</b>	Model 2004	Processor		
	<b>Logan</b>		Eeprom		
	<b>Master</b>		Eeprom		
	<b>Megane</b>	Sagem before Model 1999 Version 1	Eeprom		
		Sagem before Model 1999 Version 2	Eeprom		
		Sagem	NEC-Hardware		
		Sagem 2002 (NEC)	Eeprom		
2004		Jaeger	Processor		
by		Jaeger 908	Processor		
		Jaeger 908	Cluster-Plug		
		Visteon V1	Eeprom		
		Visteon V2	Eeprom		
		Sagem 2004	Eeprom		
	<b>Modus</b>		Eeprom		
DIGA-Soft.de	<b>Scenic</b>	Sagem before Model 1999 Version 1	Eeprom		
		Sagem before Model 1999 Version 2	Eeprom		
		Sagem	NEC-Hardware		
		Sagem 2002 (NEC)	Eeprom		
		Jaeger	Processor		
		Jaeger 908	Processor		
		Jaeger 908	Cluster-Plug		
		Visteon	Eeprom		
	<b>Safrane</b>	Version 1	Eeprom		
		Version 2	Eeprom		
		Version 3	Eeprom		
		Version 4	Eeprom		
	<b>Twingo</b>	VDO before Model 2000	Processor		
		VDO since Model 2001	Processor		
		Borg before Model 2000	Processor		

		Borg since Model 2001	Processor		
	<b>Traffic</b>		Eeprom		
	<b>Vel Satis</b>		Soldering contacts		
	<b>Vel Satis</b>	Modell 2005-	Processor (9S12)		
	<b>Megane Sagem Tacho</b>		NEC-Hardware		
<b>Rover</b>	<b>25</b>		Eeprom		
	<b>45</b>		Eeprom		
	<b>75</b>	Only diagnostic for BMW lcm owner	Diagnosis-plug (Without BMW-Kit:Eeprom)		
	<b>Minicooper</b>	Cluster + LKM	Soldering contacts		
	<b>MGF</b>		Eeprom		
<b>Saab</b>	<b>93</b>	Version 1	Eeprom		
		Version 2	Eeprom		
		Model 2003	Eeprom		
	<b>93</b>	After Model 2004	Eeprom		
	<b>95</b>	Version 1	Eeprom		
		Version 2	Eeprom		
<b>Seat</b>	All models	are identically	with Volkswagen!		
	<b>Altea</b>		Diagnosis-Plug		
	<b>Toledo</b>	Model 2002	Eeprom		
	<b>Leon 2002</b>		Eeprom		
	<b>Ibiza</b>	TRW 2003	Eeprom		
		Model 2002 VDO	Diagnosis-Plug		
		Model 2002 VDO	Eeprom		
<b>Skoda</b>	All models	are identically	with Volkswagen!		
	<b>Octavia</b>	Model 2005	Diagnosis-plug		
	<b>Octavia</b>	After Model 2005	CAN-Diagnosis		
	<b>Octavia</b>	Model 2006	CAN-Diagnosis		
	<b>Suberb</b>		CAN-Diagnosis		
<b>Smart</b>	<b>Smart</b>		Eeprom + Processor		
	<b>Roadster</b>		Eeprom + Soldering contacts		
<b>Ssang Yong</b>	<b>Rexton</b>		Processor		
	<b>Rodius</b>		Eeprom		
<b>Subaru</b>	<b>Forester</b>		Eeprom		
		Model 2002	Eeprom		
		2003	Eeprom		
	<b>Impreza</b>	before 2002	Eeprom		
		since 2002	Eeprom		
	<b>Legacy</b>		Eeprom		
		Model 2004	Eeprom		

	<b>Outback</b>				
		2003	Eeprom		
		2004	2X Eeprom		
<b>Suzuki</b>	<b>Alto</b>		Eeprom		
	<b>GSX-R 750</b>		Eeprom		
	<b>GSX-R1000</b>		Eeprom		
	<b>Bandit</b>		Eeprom		
	<b>Burgmann</b>		Eeprom		
	<b>Carry</b>		Eeprom		
	<b>Hayabusa</b>		Eeprom		
	<b>Ignis</b>		Eeprom		
	<b>Jimny</b>	Maneti Marelli 908	Processor		
	<b>Jimny</b>	Denso	Eeprom		
	<b>Liana</b>		Eeprom		
	<b>Swift</b>		Eeprom		
	<b>TL 1000</b>		Eeprom		
	<b>Vitara</b>		Eeprom		
	<b>Grand Vitara</b>		Eeprom		
	<b>XF 650</b>		Eeprom		
<b>Toyota</b>	<b>Avensis</b>		Eeprom		
		2003	Eeprom		
	<b>Picnic</b>		Eeprom		
	<b>Camry</b>		Eeprom		
	<b>Celica</b>		Eeprom		
	<b>Granvia</b>		Eeprom		
	<b>Hiace</b>		Eeprom		
	<b>HJ100</b>		Eeprom		
2004	<b>RAV 4</b>		Eeprom		
		Modell 2006	Eeprom		
by	<b>Yaris</b>		Eeprom		
		Model 2003	Eeprom		
DIGA-Soft.de	<b>Corolla</b>		Eeprom		
		Model 2002	Eeprom		
	<b>Corolla Verso</b>		Eeprom		
	<b>Landcruiser</b>	Version 1	Eeprom		
		Version 2	Eeprom		
		Model 2001	Eeprom		
		Model 2002	Eeprom		
	<b>Previa</b>		Eeprom		
	<b>Prius</b>		Eeprom		
	<b>Prado</b>		Eeprom		
	<b>Previs</b>		Eeprom		
	<b>MR 2</b>		Eeprom		
<b>Volvo</b>	<b>V40/S40</b>		Eeprom		
	<b>V40/S40</b>	Model 2004	Processor		
	<b>V60/S60</b>	912 80 Pin	Processor		
		912 112 Pin	Processor		
	<b>V60/S60</b>	Model 2004	Processor		

	<b>XC60</b>	Model 2004	Processor		
	<b>V70/S70</b>	Before Model 1999	Eeprom		
		since Model 1999 (908)	Processor		
		since Model 2001 (912) 80 Pin	Processor		
		since Model 2001 (912) 112 Pin	Processor		
	<b>XC70</b>	Modell 2004	Processor		
2004	<b>S80</b>	908	Processor		
		912 80 Pin	Processor		
		912 112 Pin	Processor		
by	<b>850</b>	Version 1	Eeprom		
DIGA-Soft.de		Version 2	Eeprom		
		Version 3	Eeprom		
		Version 4	Eeprom		
	<b>960</b>		Eeprom		
<b>Volkswagen</b>	<b>Golf 3</b>	VDO Version 1	Eeprom		
		VDO Version 1	Cluster-Plug		
		VDO Version 2	Eeprom		
		MM SW 4.0 –6.4	Eeprom		
		MM SW 4.0 –6.4	Cluster-Plug		
2004		MM SW 3.0 –3.1	Eeprom		
by		TRW	Eeprom		
DIGA-Soft.de	<b>Golf 4</b>	VDO before 2001 Version 1	Eeprom		
		VDO before 2001 Version 2	Eeprom		
		VDO before 2001	Diagnosis-Plug		
		MotoMeter before 2001 Version 1	Eeprom		
		MotoMeter before 2001 Version 2	Eeprom		
		MotoMeter before 2001	Diagnosis-Plug		
		VDO since 2001	Eeprom		
		VDO since 2001	Diagnosis-Plug		
		MotoMeter since 2001	Eeprom		
2004		MotoMeter since 2001	Diagnosis-Plug		
by		VDO since 2002	Eeprom		
		VDO since 2002	Diagnosis-Plug		
DIGA-Soft.de		MotoMeter since 2002	Eeprom		
		MotoMeter since 2002	Diagnosis-Plug		
		Version RN4 / RB8	Diagnosis-Plug (Fast search)		
	<b>Golf 5</b>	VDO	Diagnosis-Plug		
	<b>Golf 5</b>	VDO Modell 2004	Diagnosis-Plug		
	<b>Golf 5</b>	Visteon	Diagnosis-Plug		
	<b>Gol</b>	South-America	Eeprom		
	<b>Bora</b>	VDO before 2001 Version 1	Eeprom		

		VDO before 2001 Version 2	Eeprom		
		VDO before 2001	Diagnosis-Plug		
		MotoMeter before 2001 Version 1	Eeprom		
		MotoMeter before 2001 Version 2	Eeprom		
2004		MotoMeter before 2001	Diagnosis-Plug		
by		VDO since 2001	Eeprom		
DIGA-Soft.de		VDO since 2001	Diagnosis-Plug		
		MotoMeter since 2001	Eeprom		
		MotoMeter since 2001	Diagnosis-Plug		
		VDO since 2002	Eeprom		
		VDO since 2002	Diagnosis-Plug		
		MotoMeter since 2002	Eeprom		
		MotoMeter since 2002	Diagnosis-Plug		
	<b>Corrado</b>	VDO	Eeprom		
		VD202	Eeprom		
		MotoMeter	Eeprom		
		MotoMeter SW 1.3-1.8	Eeprom		
		MotoMeter SW 1.3-1.8	Cluster-Plug		
	<b>Passat B3</b>	VDO	Eeprom		
2004		VD202	Eeprom		
by		MotoMeter	Eeprom		
DIGA-Soft.de		MotoMeter	Cluster-Plug		
		MotoMeter SW 1.3-1.8	Eeprom		
		MotoMeter SW 1.3-1.8	Cluster-Plug		
	<b>Passat B5</b>	Magneti Marelli	Diagnosis-Plug		
		VDO Version 1	Eeprom		
		VDO Version 1	Diagnosis-Plug		
		VDO Version 2	Eeprom		
		VDO Version 2	Diagnosis-Plug		
		MotoMeter	Eeprom		
		MotoMeter	Diagnosis-Plug		
	<b>Passat B6</b>	VDO Version 1	Eeprom		
		VDO Version 2	Eeprom		
		MotoMeter 2003	Eeprom		
		VDO alle	Diagnosis-Plug		
		MotoMeter 2003	Diagnosis-Plug		
	<b>Passat B7</b>		Diagnosis-Plug		
	<b>T4</b>	before 10/1998	Eeprom		
		before 10/1998	Cluster-Plug		
2004		since 10/1998	Eeprom		
by		since 10/1998	Diagnosis-Plug		
		Model 2002	Diagnosis-Plug		
	<b>T5</b>		Diagnosis-Plug		
DIGA-Soft.de	<b>Sharan</b>	before Model 2001	Diagnosis-Plug		



		since Model 2001 Version 1	Eeprom		
		since Model 2001 Version 2	Eeprom		
		since Model 2001	Diagnosis-Plug		
		since Model 2002	Diagnosis-Plug		
	<b>New Beetle</b>	before Model 2001	Diagnosis-Plug		
		since Model 2001 Version 1	Cluster-Plug		
		since Model 2001 Version 2	Cluster-Plug		
		since Model 2001 Version 3	Cluster-Plug		
	<b>Lupo</b>	Version 1	Eeprom		
		Version 2	Eeprom		
			Diagnosis-Plug		
	<b>Polo</b>	VDO Version 1	Eeprom		
		VDO Version 1	Cluster-Plug		
		VDO Version 2	Eeprom		
		MM SW 4.0 –6.4	Eeprom		
		MM SW 4.0 –6.4	Cluster-Plug		
2004		MM SW 3.0 –3.1	Eeprom		
by		since Model 1998	Eeprom		
DIGA-Soft.de		since Model 1998	Diagnosis-Plug		
		TRW	Eeprom		
		TRW 2000	Eeprom		
		VDO 2002	Eeprom		
		VDO 2002	Diagnosis-Plug		
		TRW 24C08	Eeprom		
	<b>Caddy</b>	VDO Version 1	Eeprom		
		VDO Version 1	Cluster-Plug		
		VDO Version 2	Eeprom		
		MM SW 4.0 –6.4	Eeprom		
		MM SW 4.0 –6.4	Cluster-Plug		
		MM SW 3.0 –3.1	Eeprom		
		TRW	Eeprom		
	<b>Vento</b>	VDO Version 1	Eeprom		
		VDO Version 1	Cluster-Plug		
2004		VDO Version 2	Eeprom		
by		MM SW 4.0 –6.4	Eeprom		
DIGA-Soft.de		MM SW 4.0 –6.4	Cluster-Plug		
		MM SW 3.0 –3.1	Eeprom		
		TRW			
	<b>LT</b>	VDO before 1999 Version 1	Eeprom		
		VDO before 1999 Version 2	Eeprom		
			Cluster-Plug		
		VDO since 2000	Eeprom		
by		Kienzle before 1999	Eeprom		
DIGA-Soft.de			Diagnosis-Plug		

		Magneti Marelli Version 1	Processor		
		Magneti Marelli Version 2	Processor		
	<b>Phaeton</b>	V1	Eeprom		
		V2			
	<b>Phaeton</b>		<b>Diagnosis-Plug</b>		
	<b>Touareg</b>		Diagnosis-Plug		
	<b>Touran</b>		Diagnosis-Plug		
	<b>Touran</b>	Modell 2004	Eeprom		
	<b>Service</b>	all models	Diagnosis-Plug		
	<b>Service</b>	CAN Models	Diagnosis-Plug		
	<b>1551</b>	erasing the error memory CAN	Diagnosis-Plug		
<b>Yamaha</b>	<b>Drag Star</b>		Eeprom		
	<b>BT Bulldog</b>		Eeprom		
	<b>Wild Star</b>		Eeprom		
	<b>Phaser</b>		Eeprom		
	<b>Majestic</b>		Eeprom		
	<b>V-Max</b>		Eeprom		
	<b>Versity</b>		Eeprom		
	<b>YZF- R1</b>		Eeprom		
	<b>YZF-R 1</b>	Modell 2003	Eeprom		
	<b>YZF- R6</b>		Eeprom		
	<b>YZF-R6</b>	Modell 2003	Eeprom		

## The BMW-Kit for the BMW professional

### Additional module for BMW Programming E46, E38, E39, E65, X3 and X5

<b>Light-Module</b>	Programming about Processor for 912er processors
<b>Light-Module</b>	Programming with Diagnosis-Plug before 912 processors
<b>EWS Module</b>	Erasing about plug
<b>EWS Module</b>	exakte Programmierung über Stecker
<b>Keys</b>	Read out with Keyreader
<b>Keys</b>	Programming
<b>KM-Check</b>	Reading of the values from the cluster, Light-module + EWS with Diagnosis-Plug
<b>TV-Unlocking</b>	Activation of the TV Function (watch TV while you drive) for MK III Systems with Diagnosis-Plug - unlocking BMW TV also works on new Range Rover and Rover 75

## Keyreader with “ONLY-READING-FUNCTION” now also available!!!

price 399 Euro



Das DIGA-Consult System ist ausschließlich für Reparaturzwecke bestimmt. Ein geänderter Kilometerstand muß im Rechtsverkehr angegeben werden! Dieses Angebot ist freibleibend gültig before zum 31.05.2005. Für die Richtigkeit und Vollständigkeit dieser Liste wird keine Haftung übernommen. Änderungen vorbehalten.