

Model	iEasy300	iEasy300Pro	iLink400	iLink410
Image	 The image shows the Vident iEasy300 diagnostic tool, which is a compact, handheld device with a red casing. It features a color LCD screen displaying a menu with icons for various functions. Below the screen is a control panel with several buttons, including a central 'OK' button and directional arrows. A black OBD-II connector cable is attached to the top of the device.	 The image shows the Vident iEasy300Pro diagnostic tool, a handheld device with a black casing. It has a color LCD screen and a control panel with buttons similar to the iEasy300. A black OBD-II connector cable is attached to the top.	 The image shows the Vident iLink400 diagnostic tool, a larger handheld device with a black, ruggedized casing. It features a color LCD screen and a control panel with a prominent red 'OK' button and directional arrows. Three red function buttons labeled 'F1', 'F2', and 'F3' are located below the screen. A black OBD-II connector cable is attached to the top.	 The image shows the Vident iLink410 diagnostic tool, a handheld device with a black, ruggedized casing. It features a color LCD screen and a control panel with a prominent red 'OK' button and directional arrows. Three red function buttons labeled 'F1', 'F2', and 'F3' are located below the screen. A black OBD-II connector cable is attached to the top.

Vehicle coverage	All 1996 and newer cars, light-duty trucks, SUVs and minivans sold worldwide	All 1996 and newer cars, light-duty trucks, SUVs and minivans sold worldwide	AU Ford Ford, EU Ford BMW, Mini and Rolls Royce Citroen Chrysler Fiat, Abarth, Alfa Romeo and Lancia Ferrari Jaguar, Land Rover GM Vauxhall, Opel Honda Hyundai, Kia Holden Porsche Toyota, Lexus and Scion Mercedes Benz, Sprinter Maserati Mazda VW,Audi,Skoda,Seat,Bentley,Bugatti,Lamborghini,VW Commercial Volvo Renault, Dacia Subaru SsangYong Peugeot	ABS&SRS Diagnosis: Chrysler, Ford, GM, Au Ford, Acura, Daewoo, Honda, Holden, Hyundai, Infiniti, Isuzu, Kia, Lexus, Mazda, Mitsubishi, Nissan, Scion, Subaru, Suzuki, Toyota, Abarth, Alfa Romeo, Audi, Aston Martin,BMW, Bentley, Bugatti, Citroen, Dacia, EU Ford, Fiat, Ferrari,Jaguar, Lamborghini, Lancia, Land Rover, Maybach, Mercedes Benz, Maserati, Mini, Opel, Porsche, Peugeot, Renault, Rolls-Royce, Saab, Seat, Skoda, Smart, Sprinter, Vauxhall, Volkswagen, Volvo SAS Coverage: Acura, Abarth, Alfa Romeo, Audi, Bentley, Mercedes Benz, BMW, Bugatti, Chrysler, Citroen, Dacia, Fiat, GM, Honda, Holden, Hyundai, Infiniti, Jaguar, Kia, Lamborghini, Lancia, Land Rover, Lexus, Maserati, Maybach, Mini, Mitsubishi, Nissan, Opel, Peugeot, Renault, Rolls-Royce, Scion, Seat, Skoda, Sprinter, SsangYong, Subaru, Suzuki, Toyota, Vauxhall, Volkswagen EPB Service: Acura, Abarth, Audi, Alfa Romeo, BMW, Bentley, Bugatti, Citroen, Daewoo, EU Ford, Ford, Fiat, Ferrari, GM, Honda, Hyundai, Jaguar, Kia, Land Rover, Lancia, Lexus, Maserati, Maybach, Mercedes Benz, Mini, Opel, Peugeot, Porsche, Roewe, Renault, Rolls Royce, Saab, Scion, Seat, Skoda, Toyota, Vauxhall, Volkswagen, Volvo
Works on almost all electronic systems	Engine only	Engine only	√	ABS and Airbag only
OBDI and OBDII compatibility	OBDII only	OBDII only	√	√
Reads and clear codes	√	√	√	√
Reads/records/graphs live sensor data	√	√	√	√

Freeze frame data	OBDS only	OBDS only	√	√
ECU information	√	√	√	√
Multilingual menu and codes	√	√	√	√
Code troubleshooters	√	√	√	√
Hot keys for quick access of data		√	√	√
Color screen	2.4' LCD screen	2.4' FTF color screen	2.8' FTF color screen	2.8' FTF color screen
EPB Service			√	
Oil Light Reset			√	
DPF Reset			√	
Battery Configuration			√	
ABS&SRS Service			√	√
SAS(Steering Angle Sensor Calibration)			√	√
TPS/TBA(Throttle Body Alignment)			√	
Bi-directional control tests			√	√
Control module coding			√	
Other Service &Maintenance Function			√	
3 years free updates	Life-long free updates	Life-long free updates	√ Cost of purchasing another manufacturer: 60USD	√
Available Language	English,French,German,Polish,Russian,Spanish,Italian,Portuguese,Hungarian,Dutch,Sweden	Same as iEasy300	English, Spanish, German, French, Portuguese, Dutch, Swedish, Italian, Simplified Chinese, Traditional Chinese, Russian, Japanese, Korean, Polish, Hungarian and Thai	Same as iLink400


iLink440



iLink450



iAuto700



<p>General Diagnosis coverage: Chrysler, Ford, GM, Brazilian GM(For Brazilian Market Only)</p> <p>Au Ford (For Australian Market Only), Acura, Daewoo, Honda, Holden (For Australian Market Only), Hyundai, Infiniti, Isuzu, Kia, Lexus, Mazda, Mitsubishi, Nissan, Scion, Subaru, Suzuki, Ssangyong, Tata, Toyota</p> <p>Abarth, Alfa-Romeo, Aston Martin, Audi, Bentley, BMW, Bugatti, Citroen, Dacia, Fiat, EU Ford, Jaguar, Land Rover, Lancia, Lamborghini, Maserati, Maybach, Mercedes Benz, Mini, Opel, Porsche, Peugeot, Renault, Rolls-Royce, Saab, Seat, Skoda, Smart, Sprinter, Vauxhall, Volvo, Volkswagen BRILLIANCE, BYD, CHANGAN, CHANGHEAUTO, CHERY, CHERY_NE, EMGRAND, ENGLON, FOTON, GEELY, GLEAGLE, GREATWALL, JAC, KARRY, LIFAN, MAPLE, RELY,RIICH</p> <p>Oil Light Reset Coverage: Acura, Abarth, Alfa Romeo, Audi, Aston Martin, BMW, Bentley, Bugatti, Citroen, Chrysler, Dacia, Ferrari, Fiat, Ford, GM, Holden, Honda, Hyundai, Infiniti, Isuzu, Jaguar, Kia, Lancia, Lexus, Land Rover, Mercedes Benz, Mini, Mazda, Maserati, Mitsubishi, Nissan, Opel, Peugeot, Porsche, Renault, Rolls-Royce, Saab, Seat, Skoda, Scion, Subaru, Suzuki, Smart, Sprinter, Toyota, Vauxhall, Volkswagen, Volvo</p> <p>EPB Service Coverage: Acura, Abarth, Audi, Alfa Romeo, BMW, Bentley, Bugatti, Citroen, Daewoo, EU Ford, Ford, Fiat, Ferrari, GM, Honda, Hyundai, Jaguar, Kia, Land Rover, Lancia, Lexus, Maserati, Maybach, Mercedes Benz, Mini, Opel, Peugeot, Porsche, Roewe, Renault, Rolls Royce, Saab, Scion, Seat, Skoda, Toyota, Vauxhall, Volkswagen, Volvo</p> <p>Battery Configuration Coverage: Audi, BMW, Citroen, Ford, Infiniti, Jaguar, Land Rover, Lexus, Mini, Mitsubishi, Nissan, Peugeot, Seat, Skoda, Toyota, Volvo, VW</p> <p>ABS&SRS Diagnosis: Chrysler, Ford, GM, Au Ford, Acura, Daewoo, Honda, Holden, Hyundai, Infiniti, Isuzu, Kia, Lexus, Mazda, Mitsubishi, Nissan, Scion, Subaru, Suzuki, Toyota, Abarth, Alfa Romeo, Audi, Aston Martin,BMW, Bentley, Bugatti, Citroen, Dacia, EU Ford, Fiat, Ferrari,Jaguar, Lamborghini, Lancia, Land Rover, Maybach, Mercedes Benz, Mini, Opel, Porsche, Peugeot, Renault, Rolls-Royce, Saab, Seat, Skoda, Smart, Sprinter, Vauxhall, Volkswagen, Volvo</p> <p>DPF: Acura, Alfa Romeo, Audi, Bentley, Bugatti, Mercedes Benz, BMW, Chrysler, Citroen, Dacia, Fiat, GM, Honda, Hyundai, Infiniti, Kia, Jaguar, Lancia, Lamborghini, Land Rover, Lexus, Maserati, Maybach, Mini, Mitsubishi, Nissan, Opel, Peugeot, Renault, Rolls-Royce, SsangYong, Scion, Seat, Skoda, Sprinter, Subaru, Toyota, Vauxhall, Volkswagen, VW_CV</p> <p>TBA/TPS(Throttle Body Alignment): Acura, Audi, BMW, Citroen, Daewoo, Ford, Geely, GM, Honda, Hyundai, Infiniti, Kia, Land Rover, Lexus, Lincoln, Mitsubishi, Nissan, Opel, Peugeot, Porsche, Saab, Seat, Skoda, Toyota, VW</p> <p>BYD, Brilliance, Changan, Chery, Dpfv, Geely, Greatwall, Hnmazda, Huizhong, JAC, Lifan, MG, Qnlotus, Roewe, Spark, Wuling, Zzmazda, Zznissan</p> <p>Steering Angle Sensor Calibration:Acura, Abarth, Alfa Romeo, Audi, Bentley, Mercedes Benz, BMW, Bugatti, Chrysler, Citroen, Dacia, Fiat, GM, Honda, Holden, Hyundai, Infiniti, Jaguar, Kia, Lamborghini, Lancia, Land Rover, Lexus, Maserati, Maybach, Mini, Mitsubishi, Nissan, Opel, Peugeot, Renault, Rolls-Royce, Scion, Seat, Skoda, Sprinter, SsangYong, Subaru, Suzuki, Toyota, Vauxhall, Volkswagen</p>	<p>Oil Light Reset Coverage: Acura, Abarth, Alfa Romeo, Audi, Aston Martin, BMW, Bentley, Bugatti, Citroen, Chrysler, Dacia, Ferrari, Fiat, Ford, GM, Holden, Honda, Hyundai, Infiniti, Isuzu, Jaguar, Kia, Lancia, Lexus, Land Rover, Mercedes Benz, Mini, Mazda, Maserati, Mitsubishi, Nissan, Opel, Peugeot, Porsche, Renault, Rolls-Royce, Saab, Seat, Skoda, Toyota, Vauxhall, Volkswagen, Volvo</p> <p>EPB Service Coverage: Acura, Abarth, Audi, Alfa Romeo, BMW, Bentley, Bugatti, Citroen, Daewoo, EU Ford, Ford, Fiat, Ferrari, GM, Honda, Hyundai, Jaguar, Kia, Land Rover, Lancia, Lexus, Maserati, Maybach, Mercedes Benz, Mini, Opel, Peugeot, Porsche, Roewe, Renault, Rolls Royce, Saab, Scion, Seat, Skoda, Toyota, Vauxhall, Volkswagen, Volvo</p> <p>Battery Configuration Coverage: Audi, BMW, Citroen, Ford, Infiniti, Jaguar, Land Rover, Lexus, Mini, Mitsubishi, Nissan, Peugeot, Seat, Skoda, Toyota, Volvo, VW</p>	<p>General Diagnosis Coverage: Chrysler, Ford, GM, Brazilian GM(For Brazilian Market Only)</p> <p>Au Ford (For Australian Market Only), Acura, Daewoo, Honda, Holden (For Australian Market Only), Hyundai, Infiniti, Isuzu, Kia, Lexus, Mazda, Mahindra, Mitsubishi, Nissan, Perodua, Proton, Scion, Subaru, Suzuki, Ssangyong, Tata, Toyota</p> <p>Abarth, Alfa-Romeo, Aston Martin, Audi, Bentley, BMW, Bugatti, Citroen, Dacia, Fiat, Ferrari, EU Ford, Jaguar, Land Rover, Lancia, Lamborghini, Maserati, Maybach, Mercedes Benz, Mini, Opel, Porsche, Peugeot, Renault, Rolls-Royce, Saab, Seat, Skoda, Smart, Sprinter, Vauxhall, Volvo, Volkswagen, VW_CV</p> <p>BRILLIANCE, BYD, CHANGAN, CHANGHEAUTO, CHERY, CHERY_NE, EMGRAND, ENGLON, FOTON, GEELY, GLEAGLE, GREATWALL, KARRY, LIFAN, MAPLE, RELY,RIICH</p> <p>Oil Light Reset Coverage: Acura, Abarth, Alfa Romeo, Audi, Aston Martin, BMW, Bentley, Bugatti, Citroen, Chrysler, Dacia, Ferrari, Fiat, Ford, GM, Holden, Honda, Hyundai, Infiniti, Isuzu, Jaguar, Kia, Lancia, Lexus, Land Rover, Mercedes Benz, Mini, Mazda, Maserati, Mitsubishi, Nissan, Opel, Peugeot, Porsche, Renault, Rolls-Royce, Saab, Seat, Skoda, Scion, Subaru, Suzuki, Smart, Sprinter, Toyota, Vauxhall, Volkswagen, Volvo</p> <p>EPB Service Coverage: Acura, Abarth, Audi, Alfa Romeo, BMW, Bentley, Bugatti, Citroen, Daewoo, EU Ford, Ford, Fiat, Ferrari, GM, Honda, Hyundai, Jaguar, Kia, Land Rover, Lancia, Lexus, Maserati, Maybach, Mercedes Benz, Mini, Opel, Peugeot, Porsche, Roewe, Renault, Rolls Royce, Saab, Scion, Seat, Skoda, Toyota, Vauxhall, Volkswagen, Volvo</p> <p>Battery Configuration Coverage: Audi, BMW, Citroen, Ford, Infiniti, Jaguar, Land Rover, Lexus, Mini, Mitsubishi, Nissan, Peugeot, Seat, Skoda, Toyota, Volvo, VW</p>
<p>Engine, Transmission, ABS and Airbag systems only</p>	<p>/</p>	<p>√</p>
<p>√</p>	<p>√</p>	<p>√</p>
<p>√</p>	<p>√</p>	<p>√</p>
<p>√</p>	<p>√</p>	<p>√</p>

√	√	√
√	√	√
√	√	√
√	√	√
√	√	√
2.8' FTF color screen	2.8' FTF color screen	4.3" FTF color screen
	√	√
	√	√
	√	
	√	√
	√	
	√	
√	√	√
Same as iLink400	Same as iLink400	Same as iLink400



General Diagnosis Coverage: Chrysler, Ford, GM, Brazilian GM(For Brazilian Market Only)
Au Ford (For Australian Market Only), Acura, Daewoo, Honda, Holden (For Australian Market Only), Hyundai, Infiniti, Isuzu, Kia, Lexus, Mazda, Mahindra, Mitsubishi, Nissan, Perodua, Proton, Scion, Subaru, Suzuki, Ssangyong, Tata, Toyota
Abarth, Alfa-Romeo, Aston Martin, Audi, Bentley, BMW, Bugatti, Citroen, Dacia, Fiat, Ferrari, EU Ford, Jaguar, Land Rover, Lancia, Lamborghini, Maserati, Maybach, Mercedes Benz, Mini, Opel, Porsche, Peugeot, Renault, Rolls-Royce, Saab, Seat, Skoda, Smart, Sprinter, Vauxhall, Volvo, Volkswagen, VW_CV
BRILLIANCE, BYD, CHANGAN, CHANGHEAUTO, CHERY, CHERY_NE, EMGRAND, ENGLON, FOTON, GEELY, GLEAGLE, GREATWALL, KARRY, LIFAN, MAPLE, RELY,RIICH

Oil Light Reset Coverage: Acura, Abarth, Alfa Romeo, Audi, Aston Martin, BMW, Bentley, Bugatti, Citroen, Chrysler, Dacia, Ferrari, Fiat, Ford, GM, Holden, Honda, Hyundai, Infiniti, Isuzu, Jaguar, Kia, Lancia, Lexus, Land Rover, Mercedes Benz, Mini, Mazda, Maserati, Mitsubishi, Nissan, Opel, Peugeot, Porsche, Renault, Rolls-Royce, Saab, Seat, Skoda, Scion, Subaru, Suzuki, Smart, Sprinter, Toyota, Vauxhall, Volkswagen, Volvo

EPB Service Coverage: Acura, Abarth, Audi, Alfa Romeo, BMW, Bentley, Bugatti, Citroen, Daewoo, EU Ford, Ford, Fiat, Ferrari, GM, Honda, Hyundai, Jaguar, Kia, Land Rover, Lancia, Lexus, Maserati, Maybach, Mercedes Benz, Mini, Opel, Peugeot, Porsche, Roewe, Renault, Rolls Royce, Saab, Scion, Seat, Skoda, Toyota, Vauxhall, Volkswagen, Volvo

Battery Configuration Coverage: Audi, BMW, Citroen, Ford, Infiniti, Jaguar, Land Rover, Lexus, Mini, Mitsubishi, Nissan, Peugeot, Seat, Skoda, Toyota, Volvo, VW

DPF: Acura, Alfa Romeo, Audi, Bentley, Bugatti, Mercedes Benz, BMW, Chrysler, Citroen, Dacia, Fiat, GM, Honda, Hyundai, Infiniti, Kia, Jaguar, Lancia, Lamborghini, Land Rover, Lexus, Maserati, Maybach, Mini, Mitsubishi, Nissan, Opel, Peugeot, Renault, Rolls-Royce, SsangYong, Scion, Seat, Skoda, Sprinter, Subaru, Toyota, Vauxhall, Volkswagen, VW_CV

TBA/TPS(Throttle Body Alignment): Acura, Audi, BMW, Citroen, Daewoo, Ford, Geely, GM, Honda, Hyundai, Infiniti, Kia, Land Rover, Lexus, Lincoln, Mitsubishi, Nissan, Opel, Peugeot, Porsche, Saab, Seat, Skoda, Toyota, VW

BYD, Brilliance, Changan, Chery, Dpfv, Geely, Greatwall, Hnmazda, Huizhong, JAC, Lifan, MG, Qnlotus, Roewe, Spark, Wuling, Zzmazda, Zznissan

Steering Angle Sensor Calibration: Acura, Abarth, Alfa Romeo, Audi, Bentley, Mercedes Benz, BMW, Bugatti, Chrysler, Citroen, Dacia, Fiat, GM, Honda, Holden, Hyundai, Infiniti, Jaguar, Kia, Lamborghini, Lancia, Land Rover, Lexus, Maserati, Maybach, Mini, Mitsubishi, Nissan, Opel, Peugeot, Renault, Rolls-Royce, Scion, Seat, Skoda, Sprinter, SsangYong, Subaru, Suzuki, Toyota, Vauxhall, Volkswagen

√

√

√

√

√
√
√
√
√
4.3" FTF color screen
√
√
√
√
√
√
√
Same as iLink400